

Oil Field Environmental Incident Summary

Incident: 20160822085412 **Date/Time of Notice:** 08/22/2016 08:54

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: EN-MOE-154-94- 0508H-1

Field Name: ALKALI CREEK

Well File #: 17077

Date Incident: 8/21/2016

Time Incident: 11:30

Facility ID Number:

County: MOUNTRAIL

Twp: 154

Rng: 94

Sec: 5

Qtr:

Location Description:

Submitted By: Alberto Yates

Received By:

Contact Person: Troy Brunsell
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 3025 Feet

Distance Nearest Water Well: 3025 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.4	Barrels			1.37	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 10/19/2016 **Clean Up Concluded:** 9/14/2016

Risk Evaluation:

There is no immediate risk to report at this time. NO OFFSITE IMPACTS

Areal Extent:

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time. All impacts REMAINED ON SITE. No Sensitive areas were impacted due to the incident.

Action Taken or Planned:

The release occurred above ground; all oil remained in the tank dike. Upon discovery of the release, a vacuum truck was dispatched to recover as much of the released oil as practicable. The remaining impacted material will be cleaned up during the remediation process. Arrangements were made for the impacted material to be cleaned up and disposed of to an approved waste facility.

Wastes Disposal Location: The recovered waste will be taken to an approved waste disposal facility.

Agencies Involved:**Updates**

Date: 8/22/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spill remained on pad; no further follow-up is required.